





2019

Ford Fiesta

1 EcoBoost 4x2 Euro 6b petrol manual



1.1

Clean Air Index 6.6

Energy Efficiency Index



Clean Air Tests

	Laboratory test	НС	со	NO _x	PN
0.0/9	Cold Test*				
0.5 /3	Warm Test#				
0.3 /3	Eco Mode#				
0.3 /3	Sport Mode [#]				
0.0/9	Highway"				
	Road test				
2.6 /7	On-Road Drive*				
	Robustness				













Comments

In this Euro 6b form, the Fiesta scores poorly in many of the tests. Particulate number is high and, in the high-load highway test, emissions of carbon monoxide and oxides of nitrogen are also poor.

^{*} Adapted regulatory test # Additional Green NCAP tests

Energy Efficiency Tests

	Laboratory test	Energy
5.9 /10	Cold Test*	•
1.9 /3	Warm Test"	•
1.9 /3	Eco Mode#	
1.9 /3	Sport Mode#	•
3.5 /10	Highway#	
	Consumption	Fuel
	Average consumption	5.7 l /100 km
	Worst-case consumption	6.8 l /100 km













Comments

Energy efficiency is adequate in the laboratory tests except for the high-load highway test where efficiency is rated as marginal.

^{*} Adapted regulatory test # Additional Green NCAP tests

Additional Information

Greenhouse Gases **	CO2	
Cold Test*		
Warm Test#		
Eco Mode"		
Sport Mode#		
Highway#		

 $^{^{**}}$ For indication only. The assessment of greenhouse gases does not currently form part of the rating.



good adequate marginal weak

poor

^{*} Adapted regulatory test # Additional Green NCAP tests



Our verdict

Ford's ever-popular supermini, the Fiesta, has been tested here with the 1.0 EcoBoost engine which complies with Euro 6 emissions levels when tested using the previous test method but not against the latest WLTC (Worldwideharmonized Light-vehicle Test Cycle) of Euro 6d-Temp. The engine has no particulate filter and struggles with high emissions of this pollutant in all of the lab tests. Very few points are scored in the cold, warm, eco and sports mode tests as a result of particulate emissions and, in the higher-load highway test, other pollutants are also significantly increased, leading to poor performance in the Clean Air Index. On the road, emissions values are similar to those measured in the lab and particulate emissions are actually slightly reduced. The car scores much better for Energy Efficiency, with adequate or marginal performance and an index value of 6.6. All in all, an efficient engine is let down by the lack of a particulate filter, leading to high emissions of this pollutant.

Year of Publication

Mass 1,296 kg

Tyres

Tested Car
VF0JXXGAHJHR6XXXX

Engine Size 998 cc

Published CO₂ 97 g/km Emissions Class

Engine Power/Torque 74 kW/174 Nm

